

BRAZORIA COUNTY DRAINAGE DISTRICT 5

DITCH & DRAINAGE STRUCTURE INVENTORY

COMMISSIONERS:

N. LEE WALDEN, P.E. (CHAIRMAN), POSITION 1
MARK ROLLER, POSITION 2
KERRY OSBURN, POSITION 3

KALUZA INC

CONSULTING ENGINEERS & SURVEYORS

ENGINEERING FIRM No. F-1339
SURVEYING FIRM No. 10010000
3014 AVENUE I, ROSENBERG, TX 77471
PH.281.341.0808 FAX.281.341.6333

DATE:
SEPTEMBER, 1986
UPDATED: OCTOBER 26, 1987
UPDATED: DECEMBER 18, 2003
UPDATED: MAY 8, 2007
UPDATED: AUGUST 28, 2018

LEGEND:

- CULVERT (AS NOTED)
- CULVERT (AS NOTED WITH TAMBER BENTS)
- ▨ WOODEN BRIDGE
- CONCRETE BRIDGE

